

Boston Old City Hall Report

Boston, Massachusetts

Project Highlights

Historical report serves as a guide for historians in the future.

Report covered development through re-use (1875-1975).

Boston City Hall, today, right, and historic images, below.



Your Project, Our Role...

The Preservation Collaborative compiled a historic report about the history of the Old City Hall building in Boston.

The report covered history from development to re-use. It included some rare archival drawings from the initial design of the building, images and analysis.

The final report was delivered to the archives of the Boston Public Library as a historic resource guide.

The Preservation Collaborative can help clients understand their historic buildings through research and inspection. Multiple trades allow a clear report to be created under one roof.

Let The Preservation Collaborative help you learn more about your special asset, contact us today!

