

Storefront Repairs


Boston Massachusetts

Project Highlights

Our firm worked to document this historic building for repairs.

Repair work was sensitively completed on an existing cast iron storefront.

The building (right) and finished plans (below).



First Floor Plan

Your Project, Our Role...

The Preservation Collaborative worked to create construction documentation for B. Goba & Associates, P.C. for a commercial building in Boston.

Our firm provided as-built documentation, design details and paint schemes for work on a historic cast iron storefront on the first and second floors.

The Preservation Collaborative specializes in the documentation of historic properties. With more than a decade of experience in this area, we are knowledgeable about getting the task at hand complete.

We pride ourselves in working with small and large clients who have buildings of all styles, shapes and ages. We can help, so contact us to get started!

