

# Isaac Royall House HSR

*Medford, Massachusetts*

## Project Highlights

Isaac Royall House and Slave Quarters are National Historic Landmarks.

Report documents three-centuries of use and change to property, house and outbuildings.

First existing condition report for the entire property.

Preservation tool for future research, reinterpretation and restoration.



Isaac Royall House as seen from the West Facade. Isaac Royall is pictured below.



Isaac Royall By J. Copley



Royall House West Facade Drawing

## *Your Project, Our Role...*

Our firm worked on the Isaac Royall House, creating a Historic Structures Report (HSR) for the Royall House Association

Work included researching this 18th century mansion, determining significance and original features and creating an existing condition survey.

This project was completed in conjunction with restoration work on the property.

The Preservation Collaborative's diverse background and multitude of trades under one roof allow a seamless and effective report to guide preservation advocates in the right direction.

We pride ourselves in working with small and large museums. Often having multiple resources to manage, our firm assists in ensuring stainability, allowing historic properties remain at the forefront of your collection for decades to come.

