

Isaac Trafton HSR

Newfield, Maine

Project Highlights

Isaac Trafton house and barn are listed on the National Register of Historic Places.

Work included assessment of the building's chronology and occupancy, existing condition drawings, photography and inventory.

Our Firm created renderings to better demonstrate the building's architectural development.

Report addressed some needs conditions and suggested repairs and alternative uses.

Project allows sustainability for a self-sufficient resource.

Completed in conjunction with Willowbrook building documentation project.

The Preservation Collaborative researched and analyzed the Isaac Trafton House.

Based on this research, we had the building rendered as believed to have appeared in 1790 (top) and 1850 (bottom) right. Below is existing condition documentation from 2010; composite photograph below and front facade at bottom.

Renderings by Zachary Ingalls, Take Command, LLC




Your Project, Our Role...

Our firm worked on the Isaac Trafton House, creating a Historic Structures Report (HSR) for the 19th century Willowbrook Museum.

The Preservation Collaborative's diverse background and trades under one roof allow a seamless and effective report to guide preservation advocates in the right direction.

We pride ourselves in working with small and large museums. Often having multiple resources to manage, our firm assists in ensuring sustainability, allowing historic properties remain at the forefront of your collection for decades to come.



Front Elevation