
## **Project Highlights**

Isaac Royall House and Slave Quarters are National Historic Landmarks.

Existing condition drawings documents three-centuries of use and change to mansion and outbuildings.

First existing condition report for the entire property.

Preservation tool for future research, reinterpretation and restoration.



Isaac Royall House as seen from the West Facade. Isaac Royall is pictured below.





## Your Project, Our Role...

Our firm worked on the Isaac Royall House, creating existing condition plans of the mansion for the Royall House Association

Work included documenting the mansion on CAD inclusive of all 12 historic rooms on three floors, basement and attic.

This project was completed in conjunction with restoration and historic structures report.

The Preservation Collaborative specializes in the documentation of historic properties. With a decade or more of experience in this area, we are knowledgeable about getting the task at hand complete.

We pride ourselves in working with small and large museums. Often having multiple resources to manage, our firm assists in ensuring stainability, allowing historic properties remain at the forefront of your collection for decades to come.

